

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 10






FIG. 9




FIG. 11






FIG. 12



# FIG. 13



# FIG. 14







FIG. 15




**FIG. 16**



**FIG. 17**



**FIG. 18**



**FIG. 19**








FIG. 20



**FIG. 21**



**FIG. 22**




FIG. 23




FIG. 24




FIG. 25




FIG. 26




FIG. 27




FIG. 28




FIG. 29









FIG. 30




# FIG. 31

$P_m \backslash N_e$	0	400	800	.....
100				
80				
60				
⋮				


## FIG. 32A




## FIG. 32B




**FIG. 33A**




**FIG. 33B**




**FIG. 34A**




**FIG. 34B**




**FIG. 35A**




**FIG. 35B**




**FIG. 35C**



**FIG. 36A**




**FIG. 36B**




**FIG. 36C**




**FIG. 36D**



**FIG. 36E**



**FIG. 36F**



**FIG. 38**




FIG. 37

